

Inspection Field Notes for Former Plastech-Andover Facility

Facility&Address: Former Plastech Engineered Products, Inc.-Andover
205 Maple Street Extension
Andover, OH 44003
ID number: OHD068896778
Inspector: Frank Zingales (FZ)
Date: 4-26-10
Time: 0955-1115
Facility Rep: Duane Smith (DS) – Trusted Partners
Purpose of Inspection: Compliance evaluation inspection
Sample(s) Taken: No
Photograph(s) Taken: Yes

FINDINGS:

Arrived on-site and met with DS. DS provided access to facility. DS indicated that he was finishing up with removing industrial equipment. DS believed that the facility will be abandoned and go to Sheriff's sale. All utilities shut-off. Toured interior of facility with DS.

Finishing Room #2

- 2, 1000-gallon tanks (numbers C26976 & 26977) had been removed. Tanks were purchased and removed by paint equipment contractor. DS did not know if the tanks were drained prior to removal.

Finishing Room #1

- Electronic equipment (computer monitors, copiers) present. DS indicated that office related equipment was moved into area and attempted to sell on E-bay.

South Paint Kitchen

- DS indicated that nothing was done to area.
- No containers present in former hazardous waste accumulation area.

DS indicated that items on list identified by FZ were collected and taken to ECS&R. DS indicated that solvents and paints were taken to ECS&R.

Oil Room

- Plastic tray containing oil.

Molding Location #10 (EPA location B):

- Compressed gas cylinder (Oxygen) to be removed by DS.
- 2, 55-gallon drums of used oil; each $\frac{3}{4}$ full.
- Used oil/absorbent in trench drains.
- Injection molding equipment removed from area.

Molding Location #10 (EPA location A):

- 1, 55-gallon drum of used oil, ¼ full.
- Flammable compressed gas cylinder (Propylene).
- Cardboard and drums of plastic pellets.
- Office area: automotive battery.

DS indicated that private guy took oil to burn in his space heater. FZ requested name of gentlemen and explained used oil rules concerning burning of used oil.

Paint Line Area

- Paint booths were purchased and removed by paint equipment contractor.
- Observed evidence of fire. DS indicated that fire occurred at facility while contractor was removing equipment. Andover Fire Department responded.

North Paint Kitchen

- Paint related waste present in trench drains and sumps. Noted two sumps, each approximately 30" X 30" with 12" and 4"-6" of paint waste, respectively, in bottom.
- No containers present in former hazardous waste accumulation area.

Fluorescent lamps (intact and broken) and various solid wastes present throughout facility.

Inspected exterior of facility.

South/Southeast side of property:

- 3 compressed gas cylinders (propane). Label info: property of AmeriGas-Ashtabula.
- Wood pallets, plastic packaging and solid waste present.
- 3 transformers (numbers 91780, 91781 and 91782). Label indicated PCB content <50 ppm.

Southwest side of facility (EPA location C)-observed compressed gas cylinder.

Air Abatement System

- Purchased and removed by paint equipment contractor.
- Waste present in exhaust vents and filter media.
- 2, 5-gallon containers of compressor fluid.

North side-equipment present in Quonset Hut; no containerized wastes observed.

DS inquired concerning his liability at property; did removing the items on the list take care of it. FZ could not address question, informed DS to seek counsel if he chose to. FZ indicated that would acknowledge some items on list were removed by DS. FZ noted that hazardous substances remain at property and need to be addressed. FZ requested name of gentlemen who removed used oil and if DS becomes aware that facility goes for sale to notify FZ. Left site

Ohio EPA Photograph Log Former Plastech-Andover Facility April 26, 2010 All digital photographs taken and logged by Frank Zingales. DHWM Digital Camera #5 - Nikon Coolpix 5600		
Photo #	Area	Description
1&2	Interior, North Paint Kitchen	Sump with approximately 12" of paint waste in bottom.
3-5	Exterior, South/Southeast	3 compressed gas cylinders (propane).
6-8	Exterior, South/Southeast	View of wood pallets, plastic packaging and solid waste.
9-11	Exterior, Southwest side	3 transformers and label info.
12	Exterior, Southwest side	Compressed gas cylinder.
13-17	Exterior, North side	View of area where air abatement system was removed from. Waste present in vents.
18&19	Exterior, West side	View of front of facility.

Former Plastech Andover Facility
205 Maple St. Ext.
Andover, OH 44003



Photograph #1



Photograph #2



Photograph #3



Photograph #4



Photograph #5



Photograph #6



Photograph #7



Photograph #8



Photograph #9



Photograph #10



Photograph #11




Photograph #12



Photograph #13



Photograph #14



Photograph #15



Photograph #16



Photograph #17



Photograph #18



Photograph #19